

BUILDER:	Perini Navi	LOA:	37m
YEAR:	1996	BEAM:	7.52m
FLAG:	London	SPEED:	9.5 knots cruise
ACCOM:	6/7 Guests	MATERIAL:	Steel/Aluminum
LYING:	Palma de Mallorca	ENGINES:	1x Volvo





INDEX

- 1. CONSTRUCTION
- 2. MAIN CHARACTERISTICS
- 3. MACHINERY
- 4. ACCOMMODATION
- 5. GALLEY & LAUNDRY EQUIPMENT
- 6. COMMUNICATION, NAVIGATION & ENTERTAINMENT EQUIPMENT
- 7. TENDERS & TOYS
- 8. RIGS & SAILS
- 9. DECK EQUIPMENT
- 10. SAFETY & SECURITY EQUIPMENT
- 11. **REFITS**
- 12. COMMENTS
- 13. EXCLUSIONS
- **12. GENERAL ARRANGEMENT**



1. CONSTRUCTION

Steel hull, with aluminium superstructure and spars. Teak laid deck.

2. MAIN CHARACTERISTICS

General

BUILDER:	Perini Navi
LOA:	37m
LWL:	32.5m
BEAM:	7.52m
DRAFT:	3.2m
NAVAL ARCHITECT:	Perini Navi
INTERIOR DESIGNER:	Perini Navi
YEAR CONSTRUCTION:	1996
DISPLACEMENT TONNAGE:	220T
GROSS TONNAGE:	156
NET TONNAGE:	46
CLASSIFICATION SOCIETY:	ABS
MCA/COMMERCIAL CODING:	LY1 (LY2 where applicable)
<u>Capacities</u>	
FUEL:	21,300 Litres
WATER:	7.100 Litres
SPEED: Cruising speed: Max speed:	9 knots 12 knots

RANGE (NM):

3850nm @ 9 knots



3. MACHINERY

MAIN ENGINE:	Volvo Penta TAM	D 163A Turbo	ocharged	
Service	Major top end service 10,000 hours Injection pump, turbo, heat exchanger all serviced.		(2012)	
Hours:	9855 as of April 2		C	
GEARBOXES:	Twin Disc MG 1	56 Reverse re	duction	
Service	Regularly inspected	ed and maintain	ned	(2012)
STEERING SYSTEM:	•		an independent 220v emergency hand steer.	
Service	Hydraulic rams, st	eering pumps	and motors	(2012)
GENERATORS:	2x 50kW 220v No	orthern Lights I	M6414	
Service:	ABS 15 year servi	ce and inspect	ion	(2012)
Hours:	Port Starboard As of December 2	7614 hrs sind 7914 hrs sind 012		(2008) (2008)
POWER ON BOARD:	220 AC, 50Hz			
SHORE POWER:	Insulation Transfo Shore power conv		/220VAC	(new 2012) (new 2012)
BATTERIES:	Main Engine Generator Service Emergency Radio	Wet Wet Gel 2v Mastervolt C Gel 12v Mastervolt c Gel 12v	x2	(new 2013) (new 2013) (new 2012) (new 2010) (new 2010)
AIR CONDITIONING:	MarineAire CWM Output 144000 BT Serviced/new com	TU		(new 2006) (2013)
WATERMAKERS:	2x Sea Recovery 250 Litres per hou	/ Aqua Whispe r	er SRC 800-1	(new 2003)
BOW THRUSTER:				



ALFA LAVAL:	Model 303s	
AIR COMPRESSOR(S):	1x Ingersol Rand 1x service compressor for daily duties.	(new 2010)
TOILET SYSTEM:	Evac Vacuum Flush	

4. ACCOMMODATION

OWNER:	Owners' accommodation aft comprises of a full beam master stateroom with walk in wardrobe, separate office area, and large ensuite with bath.
GUESTS	To Port and Starboard are situated two twin guest cabins, with port having an additional Pullman berth, both with generous ensuite shower rooms.
CREW	There are two cabins forward, each with own bathroom and shared shower room. The cabins can be set up as either a double or two singles depending on configuration. There is also a small cabin off the main saloon suitable for use for staff or additional crew member.

5. GALLEY & LAUNDRY EQUIPMENT

OVEN: HOB:	Gaggenau EB388 (90cm) Miele Induction 5 ring KM5993	(new 2012) (new 2011)
EXTRACTION	Miele 3190	(new 2011) (new 2010)
FRIDGES	4 Perini Custom in Galley 1 Drinks fridge in Wheelhouse	
FREEZERS	2 Waeco Coolmate RSF 115	(new 2011) (new 2009)
ICEMAKER	Hoshizaki IM Series	(new 2009) (new 2008)
DISHWASHER WASHING MACHINE DRYER IRON	Miele G1222 SCI Miele W3242 Miele T8622C Miele Roller B865	(new 2008)



6. COMMUNICATION, NAVIGATION & ENTERTAINMENT EQUIPMENT

Communication Equipment

SATCOM:	Fleet 77 Irridium Sat C	Thrane & Thrane Sailor Sailor TT3020	
CELLULAR	Linksys 3G/UMTS Broadband with YachtSpot WiFi antenna Panasonic PABX		
RADIO	HF/SSB VHF	Skanti TRP 8401S SimradRS82	
Navigation Equipment			
RADAR:	Furuno 1510 Mark 3 with ARPA(new 2009)Furuno 1724C with plotter		(new 2009)
CHART PLOTTER:	MaxSea with dedicated HP Compaq computer (new 2013) Navnet 1724C		
COMPASS	Satellite Magnetic	JRC JLR 20/30 C Plath Jupiter	(new 2010) (2011)
AUTOPILOT GPS AIS B&G DEPTH	CPlath Navipilot V Furuno GP-50 Mk2 x2 FA 150 linked to Furuno radar and Maxsea (2008) Hercules 690 wind, depth, speed Furuno FCV 667		
Entertainment Equipment			
TELEVISIONS:	Saloon Master Guest	Samsung LED 46" Series 8 Grundig plasma 25" JVC plasma 20" x2	(new 2012)
ENTERTAINMENT:	Kaleidescape Server 12TB(new 2008)4 Players in Master, Guest and SaloonCockpit Music through dedicated hard-drive		



7. TENDERS & TOYS

TENDERS	Nouvarania 4.2m Yamaha 60HP 4 Stroke	(new 2008) (new 2011)
	Yamaha 15HP	
WATER SPORTS	Wakeboard Waterskis Inflatable banana, donuts etc Snorkelling equipment Wetsuits and Buoyancy aids	
8. RIG & SAILS		
RIGS:	Perini Navi Ketch Rigged Main 35m Mizzen 25m Masts unstepped All new rod rigging Bamar furlers	(2013) (new 2013) (2013)
SAILS:	Sail wardrobe All sails were new in 2008 from Quantum and have b serviced and well maintained. They have completed 5 su winter, and are still in excellent condition after spendi winters in storage. Construction is a carbon/taffeta lamina strong and durable sail yet still able to perform well in all Mainsail Mizzen Genoa 120% Staysail Fisherman (Perini style gaff less topsail)	immers and 1 ng the last 4 ate, creating a

9. DECK EQUIPMENT

ANCHORS	2x Stainless steel in recessed pockets 120m 18mm galvanised chain each side
WINDLASS	Perini Navi custom
PASSERELLES	1 Perini hydraulic passerelle 1 Perini hydraulic side-boarding ladder



10. SAFETY & SECURITY EQUIPMENT

LIFERAFTS:2x RFD 12 pax each on foredeckEPIRB:ARC Global fixSART:McMurdoFIREFIGHTING:FM200 fire suppressant in Engine Room

All other safety equipment as per MCA guidelines

11. REFITS

Refit 2001/02 Palma

- 1. ABS Special survey (5yr)
- 2. Rigs pulled and serviced
- 3. Furlers serviced
- 4. Generator dry exhausts replaced
- 5. Main engine dry exhaust replaced
- 6. New main engine (warranty)
- 7. Paint topsides, superstructure and rigs

Refit 2002/03 Palma

1. New water makers

Refit 2003/04 New Zealand

- 1. ABS intermediate survey
- 2. Water tanks sandblasted and repainted.
- 3. Zero hours on generators
- 4. Replaced shaft bearings

Refit 2005/06-Palma

- 1. ABS Special Survey (10yr)
- 2. Overhaul variable pitch system
- 3. Paint grey and black tanks
- 4. Paint topsides and super structure
- 5. Replace foredeck and side deck teak
- 6. New air conditioning system
- 7. New soft furnishing throughout yacht

Refit 2007-08 Palma

- 1. Rigs pulled and service.
- 2. Rigs painted
- 3. Side boarding ladder and passerelle stripped and repainted
- 4. Propeller, prop shaft and rudder service.
- 5. New sails

2008 Autumn

- 1. Paint Transom
- 2. Variable Pitch service
- 3. Keel Ram service
- 4. Generators overhaul (zeroed)



Refit 2009-10

- 1. Paint topsides
- 2. Carpets replaced
- 3. New emergency battery installation as required by MCA/ABS
- 4. New deck winches x4
- 5. New 60hp tender outboard

Refit 2011-12

- 1. ABS Special Survey (15yr)
- 2. Propeller dismantled and serviced.
- 3. Shaft pulled, dismantled and serviced
- 4. Cederval shaft seals
- 5. Rudder removed, rudder bearings replaced.
- 6. Steering gear serviced
- 7. Waste tanks were sandblasted back to bare steel, corrosion treated and repainted.
- 8. Fresh water tanks painted.
- 9. Main engine exhaust muffler box and the exhaust discharge hull plating replaced.
- 10. New teak on foredeck
- 11. New wheel house teak trim
- 12. Main engine overhaul 10,000hr
- 13. New house/service batteries
- 14. Super-structure paint
- 15. Fuel tanks emptied and cleaned.
- 16. Bilge painting throughout
- 17. New generator mounts
- 18. New air handlers
- 19. New Gaggenau oven
- 20. New shore power transformer

Winter 2012-13

- 1. Rig removed, service and paint
- 2. Extensive varnish throughout interior and exterior
- 3. Variable pitch service
- 4. Captive winch service
- 5. Re-caulk windows
- 6. New sheets and halyards

During all yard periods, particular attention was paid to planned maintenance, which included regular servicing of all machinery, bilge and fire pumps and related systems, through hull fittings and valves, all other pumps and pipework, varnish programs and upgrading of equipment.



12. CAPTAIN'S COMMENTS:

Northern Spirit is a solid, well proven sailing yacht with one circumnavigation, multiple Atlantic crossings and Mediterranean passages. She has been professionally maintained, without financial hesitation from the current owner for the last 13 years, and has benefited from continuity of crew throughout that period. Northern Spirit has a very successful charter history and is ready to go, in excellent condition.

13. EXCLUSIONS

- 1. Dive equipment
- 2. Kayaks
- 3. Windsurfers and equipment